



Memorandum

TO: Chief Auxier
FROM: DC DeLeeuw
DATE: Corrosion Quotes for E35 & E36
RE: January 18, 2012

Quotes were obtained for the corrosion repair work for Engines 35 & 36 in September 2011 in anticipation of the budget process for 2012. The quotes attached were obtained in September and state they are only good for 90 days. I did contact Pierce and explained our approval process for this work. They are willing to extend the quote for another 60 days at the same price.

If you have any questions, please feel free to contact me.

SD/tt



Midwest Regional Service Center
816 Commercial Avenue
Weyauwega, WI 54983
(920) 867-2142

09-06-11
Neenah-Menasha Fire Rescue
Corrosion Repair EA665

Repair corrosion and repaint at the following locations:

- Passenger side cab (white) below crew cab window
- Passenger side crew cab door (white) on window post
- Passenger side body front post (R&R catwalk)
- Passenger side body fender complete
- Passenger side rear compartment door both lower corners
- Passenger side rear bulkhead below amber light
- Passenger side front body corner
- Passenger body inner liner
- Drivers side rear door at hinge corner
- Drivers side body fender panel complete up to catwalk
- Drivers side body inner liner
- Drivers side horizontal compartment door – replace
- Drivers side front body corner
- Drivers side rear corner of crew cab
- Drivers side crew cab door - lower section of door
- Estimated cost.....\$ 15,564.00

NOTE: Additional corrosion may be found after disassembly

PRICING GOOD FOR 90 DAYS FROM ABOVE DATE.



Midwest Regional Service Center
816 Commercial Avenue
Weyauwega, WI 54983
(920) 867-2142

09-06-11
Neenah-Menasha Fire Rescue
Corrosion Repair EB374

Repair corrosion at the following locations:

- Passenger side below windshield by door hinge
- Passenger side cab panel above fenderette
- Passenger side crew cab door at window
- Three compartment doors on Passenger side by hinges
- Passenger side rear ladder rack pivot block
- Drivers side rear compartment corner by reflector
- Drivers side body fender panel by light
- Drivers side front free door both lower corners
- Drivers side lock door lower corner by hinge
- Drivers side cab above fenderette
- Drivers side crew cab step, triangle, and panel under scotchlite
- Drivers side cab triangle forward of wheel
- Driver's side cab step under scotchlite

Estimated cost.....\$ 13,635.00

NOTE: Additional corrosion may be found after disassembly.

PRICING GOOD FOR 90 DAYS FROM ABOVE DATE.