

# APPLETON STRUCTURAL STEEL CO.

P.O. Box 326  
Appleton, Wisconsin 54912-0326

## Material Safety Data Sheet

Company Appleton Structural Steel Co. P.O. Box 326 Appleton, Wisconsin 54912-0326	Issue Date June 26, 1986	Identification Carbon & Alloy
Trade Name (Common Name or Synonym) Carbon, Alloy, Steels	Phone Number (414) 725-8515	
Chemical Name Steel	Form Bar, Sheet, Plate, Tubing, Structurals	

### I. INGREDIENTS

Material or Component	CAS Number	% Weight	Exposure Limits	
			OSHA PEL (mg/m <sup>3</sup> )	ACGIH TLV (mg/m <sup>3</sup> )
Base Metal Iron (Fe)	7439-89-6	Balance	10 (Fe <sub>2</sub> O <sub>3</sub> Fume)	5.0 (Fe <sub>2</sub> O <sub>3</sub> Fume)
Alloying Elements				
Carbon (C)	7440-44-0	0.01 - 1.5	None Listed	None Listed
Chromium (Cr)	7440-47-3	0.01 - 12	1.0 as chrome	0.5 as chrome
Copper (Cu)	7440-50-8	0.04 - 0.7	0.2 as copper; 1.0 as dust	0.2 as fume; 1.0 as dust
Lead (Pb)	7439-92-1	0.15 - 0.35	0.05 as fume & dust	0.15 as dust and fume
Manganese (Mn)	7439-96-5	0.05 - 2.0	5 as manganese	5 as dust; 1 as fume
Molybdenum (Mo)	7439-98-7	0.01 - 1.10	15 as insoluble compds	10 as insoluble compds
Nickel (Ni)	7440-02-0	0.01 - 10	1.0 as Nickel	1.0 as Nickel
Phosphorous (P)	7723-14-0	0.15 Max	0.1 as Phosphorous	0.1 as Phosphorous
Silicon (Si)	7440-21-3	0.15 - 2.20	None Listed	10 total dust
Sulfur (S)	7704-34-9	0.001 - 0.35	13 sulfur dioxide	5 sulfur dioxide
Tungsten (W)	7440-33-7	0 - 18	None Listed	5 insoluble compds
Vanadium (V)	7440-62-2	0.01 - 1.0	0.5 dust; 0.1 fume	0.05 dust and fume
Zinc (Zn) coating	1314-13-2	10 Max	5.0 as fume	5.0 as fume

Note: The above listing is a summary of elements used in alloying steel. Various grades of steel will contain different combinations of these elements. Trace elements may also be present in minute amounts.

### II. PHYSICAL DATA

Material is (At Normal Conditions): <input type="checkbox"/> Liquid <input checked="" type="checkbox"/> Solid <input type="checkbox"/> Gas <input type="checkbox"/> Other	Appearance and Odor Gray-Black With Metallic Lustre — Odorless		
Acidity/Alkalinity ph = NA	Melting Point Approx 2750°F	Specific Gravity (H <sub>2</sub> O = 1) — 7	Vapor Pressure (mm Hg at 20°C) NA
	Boiling Point NA °F	Solubility in water (% by weight) — NA	

### III. PERSONAL PROTECTIVE EQUIPMENT

Respiratory Protection NIOSH approved dust/mist/fume respirator should be used during welding or burning if OSHA PEL or TLV is exceeded.	Hands, Arms, and Body Use appropriate protective clothing such as welders aprons & gloves when welding or burning. Check local codes.
Eyes and Face Safety glasses should always be worn when grinding or cutting; face shields should be worn when welding or burning.	Other Clothing and Equipment As required

### IV. EMERGENCY MEDICAL PROCEDURES

Inhalation:	Remove to fresh air; if condition continues, consult physician.
Eye Contact:	Immediately flush well with running water to remove particulate; get medical attention.
Skin Contact:	If irritation develops, remove clothing and wash well with soap and water. If condition persists, seek medical attention.
Ingestion:	If significant amounts of metal are ingested, seek medical attention.

## V. HEALTH/SAFETY INFORMATION

### HEALTH

Steel products in the natural state do not present an inhalation, ingestion, or contact health hazard. However, operations such as welding, burning, sawing, brazing, grinding, and possibly machining, which results in elevating the temperature of the product to or above its melting point or results in the generation of airborne particulates may present hazards. The above operations should be performed in well ventilated areas. The major exposure hazard is inhalation.

Effects of overexposure are as follows:

**Acute:** Excessive inhalation of metallic fumes and dusts may result in irritation of eyes, nose, and throat. Also high concentrations of fumes and dusts of iron-oxide, manganese, copper, zinc, & lead may result in metal fume fever. Typical symptoms consist of a metallic taste in the mouth, dryness and irritation of the throat, chills and fever, and usually last from 12 to 48 hours.

**Chronic:** Chronic and prolonged inhalation of high concentrations of fumes or dust of the following elements may lead to the conditions listed opposite the element:

Iron (Iron-oxide) - Pulmonary effects, siderosis.

Manganese - Bronchitis, pneumonitis, lack of coordination.

Chromium - Various forms of dermatitis, inflammation and/or ulceration of upper respiratory tract, and possibly cancer of nasal passages and lungs. Based on available information, there does not appear to be any evidence that exposure to welding fume induces human cancer.

Nickel - SAME AS CHROMIUM

Copper - Pulmonary effects.

Vanadium - No reported cases of exposure to vanadium.

Molybdenum - Pain in joints, hands, knees and feet.

Tungsten - Some evidence of pulmonary involvement such as cough.

Lead - Prolonged exposures can cause behavioral changes, kidney damage, periphery neuropathy characterized by decreased hand-grip strength and adverse reproductive effects.

Zinc - None reported.

Occupational Exposure Limits

See Section I.

### FIRE AND EXPLOSION

Flash Point	NA	°F	Auto Ignition Temperature	NA	°F	Flammable Limits in Air	Lower NA %	Upper NA %	Extinguishing Media	NA
-------------	----	----	---------------------------	----	----	-------------------------	------------	------------	---------------------	----

Fire and Explosion Hazards	None	Extinguishing Media Not to be Used	NA
----------------------------	------	------------------------------------	----

### REACTIVITY

Stability	<input checked="" type="checkbox"/> Stable <input type="checkbox"/> Unstable	Incompatibility (Materials to Avoid)	Reacts with strong acids to form hydrogen gas.
-----------	--	--------------------------------------	--

Conditions to Avoid	<b>Keep Area Well Ventilated</b> Non-ventilated areas when cutting, welding, burning, or brazing; avoid generation of airborne dusts and fumes.
---------------------	--

Hazardous Decomposition Products	Metallic oxides.
----------------------------------	------------------

## VI. ENVIRONMENTAL

Spill or leak procedures	Special Precautions: Use good housekeeping practices to prevent accumulation of dust and to keep airborne dust to a minimum.
--------------------------	--

Waste Disposal Method	Dust, etc. — follow federal, state, and local regulations regarding disposal.
-----------------------	---

## VII. ADDITIONAL INFORMATION

Disclaimer	The information in this MSDS was obtained from sources which we believe are reliable. However, the information is provided without any representation or warranty, expressed or implied regarding the accuracy or correctness.  The conditions or methods of handling, storage, use and disposal of the product are beyond our control and may be beyond our knowledge. For this and other reasons, we do not assume responsibility and expressly disclaim liability for loss, damage or expense arising out of or in any way connected with the handling, storage, use or disposal of the product.
------------	---